



BAGS SPORT di Tutino Michele.
Scalo Ferroviario snc 94017 REGALBUTO (EN)-ITALY
Tel:+39 09351960593
P.IVA 03101770109 C.F.TTNMHL61H16D969L

SAFETY NOTICE.

CORRUGATE TUBE/INFLATOR JJ-CCR BCD

Dear Customer,

We have discovered a quality issue on corrugate of the inflator mounted on the JJ-CCR bcd.

This item has been supplied from our company and if you have one of these ones, please contact us by email with the following informations:

- Name, address, country
- Serial number

PRODUCTS AFFECTED:

The quality issue concerns only the following products:

Inflator Corrugated Hose

SERIAL NUMBERS:

from **22.27.964** to **22.28.000**

from **22.28.002** to **22.28.064**



from **22.29.180** to **22.29.379**

DESCRIPTION OF THE PROBLEM:

In a limited number of cases, the corrugated hose may show early signs of wear in the bending area near the fitting. Over time, this could lead to air leakage. The affected item can be identified by the serial number, as shown in the image below.

WHAT SHOULD YOU DO NOW

If you own one of the products listed in this notice and the serial number falls within the affected range, we kindly recommend replacing the corrugated hose as a precaution. Please contact us by email with your name, address, country, and serial number, and include a photo of the corrugated hose in the indicated area as well as a photo of the serial number, so we can assist you with the replacement process.



We apologize for the inconvenience that this problem causes you. We believe in safety and we care about our customer and about all divers. We will do our utmost to make the process of replacing the corrugate tubes as seamless as possible. Your cooperation is deeply appreciated. Should you have any additional question or concern please contact us at the following email address:

bags.sport@gmail.com

Michele Tutino
BAGS SPORT